



## Bulkhead Adaptor





PART NUMBER	THREAD "A"	"B"
3AAO41XA1012AA	5/8-24	3/8
3AAO41XA1216AA	3/4-20	1/2
3AAO41XA1624AA	1-20	3/4
3AAO41XA2132AA	1-5/16-18	1
3AAO41XA2440AA	1-1/2-18	1-1/4

## Through Bulkhead Adaptor



PART NUMBER	THREAD "A"	"B"
3AAO42XA1012AA	5/8-24	3/8
3AAO42XA1216AA	3/4-20	1/2
3AAO42XA1624AA	1-20	3/4
3AAO42XA2132AA	1-5/16-18	1
3AAO42XA2440AA	1-1/2-18	1-1/4


## Transitions



PART NUMBER	THREAD "A"	"B"
3AAO**XA0910AA	9/16-24	5/16
3AAO**XA1216AA	3/4-20	1/2
3AAO**XA1724AA	1-1/16-18	3/4
3AAO**XA2132AA	1-5/16-18	1
3AAO**XA2640AA	1-5/8-18	1-1/4

— Add correct digits for specific Transition required

## Transition Joiners



PART NUMBER	THREAD A	A' ACROSS FLATS	THREAD B	B' ACROSS FLATS
3AC048XA0909AA	9/16-24	11/16	9/16-24	11/16
3AC048XA1209AA	3/4-20	7/8	9/16-24	11/16
3AC048XA1212AA	3/4-20	7/8	3/4-20	7/8
3AC048XA1712AA	1-1/16-18	1-3/16	3/4-20	7/8
3AC048XA1717AA	1-1/16-18	1-3/16	1-1/16-18	1-3/16
3AC048XA2117AA	1-5/16-18	1-7/16	1-1/16-18	1-3/16
3AC048XA2121AA	1-5/16-18	1-7/16	1-5/16-18	1-7/16
3AC048XA2621AA	1-5/8-18	1-3/4	1-5/16-18	1-7/16
3AC048XA2626AA	1-5/8-18	1-3/4	1-5/8-18	1-3/4